



VEHICLE REGULAR MAINTENANCE AND REPAIR RECORD



First Service Due WARNING	
Service Type A 2	Service Type B
Mattern GmbH Blankensteinstr. 43-48, 32257 Bünde Telefon: 0 52 23 / 99 29 60 	
Odometer Reading 24180 L	Date 21.07.2023
Brake Fluid Change	Coolant Change
ESS Equilibrium Inspection	

Service Due	
Service Type A	Service Type B
Signature _____	
Odometer Reading	Date
Brake Fluid Change	Coolant Change
ESS Equilibrium Inspection	

Service Due	
Service Type A	Service Type B
 Zoller & Co. KG 384 Bodenseestr. 100 88469 Mündlach Tel. 089/82006949	
Odometer Reading 18163	Date 05/25
Brake Fluid Change	Coolant Change
ESS Equilibrium Inspection	

Service Due	
Service Type A	Service Type B
Signature _____	
Odometer Reading	Date
Brake Fluid Change	Coolant Change
ESS Equilibrium Inspection	

ANTI PERFORATION INSPECTION RECORD

Anti Perforation Inspection Due	
<div style="text-align: center;"> Mattern GmbH Blankensteinstr. 43-48, 32257 Bünde Telefon: 0 52 23 / 99 29 60</div>	
Signature 	
Odometer Reading 24180 L	Date 21.07.23
Repairs Due	

Anti Perforation Inspection Due	
Signature _____	
Odometer Reading	Date
Repairs Due	